

**Tank Inspector(s)** J. Martin (STI #AC 32455) and M. Emert

**Name Plate/Construction**

**Circumference:** 38.20'

Steel  Stainless Steel  Plastic  Aluminum  Fiberglass

Build Date 2000 Manufacturer Palmer Manufacturing and Tank

Build Std:  API-650  API-12C  API-12F  UL-142  Re-Erected  Unknown

Date Last External \_\_\_\_\_ Date Last Internal \_\_\_\_\_

**Name Plate Data**

Dia/Width: 12.00 ft Must be <=30 ft

Height: 42.00 ft Must be <=50 ft

Length: \_\_\_\_\_ ft

Capacity: 35,291 GAL

STI Not applicable for tanks over 50,000 Gal.

**Product Service** Basestock #8

**Specific Gravity** 1.0

Ambient  Heated

Refrigerated

Operating Temperature \_\_\_\_\_ F

STI Not applicable for heated tanks over 200°F



**Tank Description**

Vertical  Horizontal  Box  Tote  Other \_\_\_\_\_

**Foundation:**  Grade  Ringwall  Concrete Pad  Saddles  Skids  Other

**Bottom:**  Welded  Riveted  Bolted  N/A Year Installed: \_\_\_\_\_

No Coating  Thin Coating  Thick Coating

Pan Type  Cathodic Protection  Double Bottom  Leak Detection

**Shell:**  Welded  Riveted  Bolted  Combination

Lap welded  Insulated  Double Wall  Containment Vessel

**Horizontal Tank Heads:**  Flat  Hemispherical  Dish

**Roof:**  Cone  Flat  Geo-Dome  Dome  Open/None  N/A

**Roof Access:**  Spiral Stair  Radial Stair  Catwalk  Ladder  None

**1. Spill Control**

None

Containment AST  Dbl Wall/Bottom  Dike Area  Remote Impound  in Building

**2. CRDM (Continuous Release Detection Method)**

None

**RPB (Release Prevention Barrier)**

Type  Concrete Pad  Liner  Steel Plate  Other \_\_\_\_\_

**Double Wall/Bottom** with Interstitial Space

OK  Not OK  Not Checked

**Elevated**

**3. AST Category**

Category   1  

- 1 Any Tank with Both Spill Control and CRDM
  - 2 Single wall AST in contact with ground NO CRDM Has Spill Control
  - 3 Single wall AST in contact with ground has CRDM NO Spill Control
- Vertical AST on concrete pad CRDM has NO Spill Control  
Single/Double wall AST Has CRDM NO Overfill Protection

**4. Venting**

- Open vents not elevated 12 feet  Open vents not vented outside building
- Uses long bolted Manway as emergency vent  Vapor recovery system

Primary Vent  Open  Pressure/Vacuum  Pressure Size:   8.00"  

Secondary Vent  Open  Pressure/Vacuum  Pressure Size: \_\_\_\_\_

Emergency Vent  Open  Pressure/Vacuum  Pressure Size: \_\_\_\_\_

Interstice Vent  Open  Pressure/Vacuum  Pressure Size: \_\_\_\_\_

**5. Comments**

The tank was located inside a building.

The tank had an 8-inch open vent. The open vent extended to the lower level of the tank.

The open vent was not vented outside the building.

**1. Foundation** **Concrete Pad**

**Anchorage:**  No Anchors  Cable Tie Downs  Anchor Bolts  
Number of Anchors:   4   Size of Bolt (in)  1.00  Height (in)  11.00   
Thickness of top plate (In)    Thickness of side plate (In)   

**Ringwall/Pad** Distance from Bottom extension to edge (in)  5.00  Min  7.00  Max  
**Dimensions:** Distance from top surface to grade (in)  23.00  Min  24.00  Max

**Support** Number of supports:    Space between Supports (in)     
**Dimensions:** Size of supports (in):    Height of supports (in):     
 No Pad Plate  Pad Plate  Stitch welded pad plate  Seal welded pad plate

**2. Undesirable Foundation Conditions**

- Grade against tank  Washout  Voids under tank  Hairline Cracks in concrete
- Large Cracks in concrete (>1/8")  Exposed rebar  Discontinuous Ringwall
- Corrosion of supports  Anchor Bolt Corrosion  Bottom extension corrosion

**3. Undesirable Area Conditions**

- Obvious settlement  Water Against tank  Drainage toward tank  Excessive debris
- Vegetation by tank  Moss under bottom  No Containment Dike/Wall
- Damaged Containment Dike/Wall  Product residue  Wet Product by Tank

**4. Comments**

The tank was located inside a building.

---

---

---

---

---

---

---

---

---

---

**1. External Tank Shell**

*Welded*

- Seams Covered  Rivets Unsealed  Rivets Sealed  Rivets Welded  
 No Pad Plates Under Shell Brackets  No Ice shields on All Item <2"  Foam System

**2. Coating Conditions**

Like New  Good  Fair  Poor  No Coating

- Peeling  Cracking  Thinning  Rust Stained  Primer Only  Areas not Coated

**Insulation Conditions**

Like New  Good  Fair  Poor

- Sprayed  Corrugated/ Banded  Smooth Metal  Areas Removed  
 Tears  Damaged  Holes  Penetrations Not Sealed  Wet under Insulation

**3. Undesirable Shell Conditions**

- Weld Seam Corrosion  Weld Pinholes  Arc Strikes  Weld Porosity  Weld Slag  
 Weld Cracks  Weld Undercut  Lack of Fusion  Holes in Shell  Gouges in Shell  
 Inactive Corrosion  Active Corrosion  Surface Corrosion  Corrosion Damage  
Deepest Shell Corrosion Found: \_\_ Height above Grade \_\_  Needs Evaluation

**4. Shell Distortion and Buckling**

- Peaking  Banding  Lower Shell Distortion  Upper Shell Distortion  Torn Plate  
 Distortion around Nozzles/Repairs  Minor Buckles  Major Buckles  Sharp Creases

**5. Possible Improper Construction Practices**

List Items Below

- Square Corner Inserts/Pads  Lap Patches  Unreinforced Penetration  Split Repad  
 No Telltale Hole in Repad  Plugged Telltale Hole in Repad  Improper Weld Space  
 Insufficient Reinforcement  Undersize Insert  Cover Plate Thin  Flange Thin

The repads of Shell Items C, I, and J did not have telltale holes.

The weld spacing of Shell Items C and G did not meet API standards

Shell Nozzles A, G, and H were over 2 inches in diameter and did not have repads.

**6. Ground cables**

Quantity 1

- None Found  Not Attached  Broken  Improper Attachment



**7. Level Gauge    Manufacturer DP Hanjo    Product Height:     FT**

- Float with Gauge    Target Board    Electronic    Floats, Cables Guides not Attached
- Not Working    Conduit damaged    Needs Service

**8. Top Angle Wind Girder**

- None    Toe In    Toe Out    Corrosion    TA Weld Size Greater than 3/16"
- Damaged Welds    Buckled    Coating Failure    Holds Water    Buckled

**Top Angle:** Vertical (in)  2.50  Horizontal (in)  2.50  Thickness (in)  0.252 

**Wind girder:** Vertical (in)     Horizontal (in)     Thickness (in)    

Distance from Top of Tank (in):    

**9. Shell Vents and Overflows**

- None    Indicator Holes    Screens Missing/Damaged    Over Stairway    Geo Dome

Number of Vents:     Size (in):     Distance from roof (in):    

Number of Overflows:     Size (in):     Distance from roof (in):    

**10. Comments**

The coating on the external shell and appurtenances was in good condition.

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

**1. Internal Tank Shell**

*Welded*

- Product Build-Up  Product Residue  Lower Shell Coated  Entire Shell Coated
- Shell Not Inspected  Shell Welds Not Inspected

**2. Undesirable Shell Conditions**

- Weld Seam Corrosion  Weld Pinholes  Weld Porosity  Weld Slag  Weld Cracks
  - Weld Undercut  Lack of Fusion  Arc Strikes  Holes in Shell  Gouges in Shell
  - Weld Burrs  Minor Shell Corrosion  Shell Corrosion Damage
- Deepest Shell Corrosion Found: \_\_ Height above Bottom \_\_  Needs Evaluation

**5. Possible Improper Construction Practices**

List Items Below

- Lap Patches  Item Penetrates but Not Welded  Hot Tap  Drilled Hole for Coupling
  - No Pads on Gauge Pole Supports  No Pads on Datum Plate Supports  Undercut
  - Incomplete Shell Weld  Lack-of-Fusion  Cracked Weld  Welds Not Visible
- 
- 

**5. Internal Piping and Supports**

- No Pads on Pipe Supports  Pipe Support Welded to Both Pipe and Bottom
  - Inadequate Pipe Supports  Corrosion on Piping  Broken Welds  No Diffuser
  - No Suction Trough  Center Suction / Fill  Has Floating Suction Line
- 

**6. Comments**

There was product residue on the internal shell.

---

There was a pinhole in the internal weld of Shell Item E. There was undercut and pinholes in the internal welds of Shell Items F.

---

---

---

---



---



Height is measured from bottom to the centerline of the item. Weld spaces are measured toe-to-toe of the welds.

ID	Size	TT hole	Shape*	Description	Location	Height	Repad/Insert			Neck Thicknesses				Weld Space	To**
							Width	Height	t	Top	Bottom	Left	Right		
A	24.00			Manway	0.00	29.00					0.388			17.00	CW
B	1.00			Coupling	3.20	30.00								29.00	CW
C	2.00			Nozzle - Steam	5.10		10.00	10.00	0.259		0.241			1.00	CW
D	1.00			Coupling	6.40	24.00								23.00	CW
E	1.00			Coupling	11.60	24.00								11.50	CW
F	5.00		1	Coupling - Pressure	11.60	6.00	10.00	10.00	0.252					0.25	CW
G	4.00			Nozzle	13.30	32.00					0.225			11.00	CW
H	4.00			Nozzle	14.10	24.00					0.230			15.00	CW
I	8.00			Nozzle w/ Mixer	26.00	37.00	22.00	22.00	0.249		0.290			23.50	CW
J	2.00			Nozzle - Steam	33.00	9.00	10.00	10.00	0.252		0.215			4.00	CW
K	4.00			Nozzle (blinded)	14.90	8.00					0.230			5.00	CW
L	3.00			Nozzle	11.70	Ring 7									
M															
N															
O															
P															
Q															
R															
S															
T															
U															
V															
W															
X															
Y															
Z															
AA															
BB															

\*\* TS=Tombstone or low type repad, CW=Cornerweld, HW= Horz. weld, VW=Vertical Weld, R#=Repad of Item #, #-Weld of Item#, PB=Pan Bottom weld



- | Couplings/Other
- ┆ Nozzles
- ┆┆ Manway
- Ladder
- Catwalk/Platform
- ┆┆ Stairs

		Job No:	652009	
		Tank Num:	DVOP8	
		Date:	06-08-2021	
Customer:	AGP			
Location:	Hastings, NE			
	Diameter:	12.00	Height:	42.00
	Drawn by:	A Frye	Rev:	

STI-INTERNAL



Company: AGP  
 Location: Hastings, NE

Job ID: 652009  
 Date: 6/8/2021  
 Tank: DVOP8

Course	Height (in)	Shell Material	Joint Type*	Shell Thicknesses (in)		
				Bottom	Middle	Top
1	72.00		BW	0.248	0.249	0.250
				0.250	0.247	0.248
				0.250	0.249	0.247
				0.246	0.248	0.249
2	72.00		BW	0.248	0.250	0.250
3	72.00		BW	0.250	0.248	0.246
4	72.00		BW	0.249	0.249	0.249
5	72.00		BW	0.245	0.248	0.248
6	72.00		BW	0.246	0.247	0.248
7	72.00		BW	0.250	0.250	0.249
8						
9						
10						

\* Joint Type: BW= Butt Weld, LW= Lap Weld, LR# = Lap Riveted (num of rivets), BR= Riveted Butt joint (Num Rivets on one side), BLT=Bolted

Total Height

Minimum Thickness written in **Blue Font**

Enter Vertical seam Location in CCW order from Start point.

1		11		21		31
2		12		22		32
3		13		23		33
4		14		24		34
5		15		25		35
6		16		26		36
7		17		27		37
8		18		28		38
9		19		29		39
10		20		30		40

Second Course offset \_\_\_\_\_

Third Course offset \_\_\_\_\_

**1. Tank Roof** **Cone**

- No Access  Limited Access  Access Not Safe  No Safety Tie Off  
Slope, Run 24 inches Rise (in): 3.00

**2. Coating Conditions**  Like New  Good  Fair  Poor  No Coating

- Peeling  Cracking  Thinning  Primer Only  Areas Not Coated

- Insulation Conditions**  Like New  Good  Fair  Poor  
 Sprayed  Corrugated/ Banded  Smooth Metal  Areas Removed  
 Tears  Damaged  Holes  Penetrations Not Sealed  Wet under Insulation

**3. Undesirable Roof Conditions**

- Weld Seam Corrosion  Weld Pinholes  Weld Cracks  Holes in Roof  
 Inactive Corrosion  Active Corrosion  Surface Corrosion  Corrosion Damage  
 No Safety Bars on >30" Openings Thinnest RWT Found: 0.247"  Needs Evaluation

**4. Roof Distortion and Buckling**

- Excessive Waviness  Areas Holding Water  Settlement of Support Structure  
 Torn Plates  Sharp Creases  Roof Joint Not Frangible (3/16")

**5. Vents and settings** List vent sizes and settings below

- Open Vents  Pressure/Vacuum Vents  Peripheral Vents  Flame Arrestor  
 Missing/Damaged Screens  Vents Need Service  Less than 8" Center Vent with IFR  
The tank had an 8-inch open vent. The open vent extended to the lower level of the tank.  
The open vent was not vented outside the building.

**6. Comments**

The coating on the external roof and appurtenances was in like new condition.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**1. Internal Tank Roof**

Structurally Supported     Self Supporting (No Structure)

Record column radius location and number of columns

Center	Bay 1	Bay 2	Bay 3	Bay 4
Radius    0				
Number    0				

**2. Column Type, Size and Conditions**

Structural Steel     Steel Pipe     Both Types

Dimensions (in)	Center Column	Outer Columns
Size of Members		

- Welded     Riveted     Bolted     Bowed     Twisted     Out-of-Plumb     Damaged  
 Corroded     Broken Welds     No Drain Hole in Pipe

**3. Column Base Type, Size and Conditions**

H-Shaped     T-Shaped     Flat Plate

Dimensions (in)	Center Base	Outer Bases
Size of Members		
Bearing Plate		

- Welded     Riveted     Bolted     Damaged     Welded to Bottom     No Guide Clips  
 Insufficient Guide Clips     Corroded     No Bearing Plate     Not Seal Welded

**4. Rafter Conditions**

- Bowed     Twisted     Hanging     Sagging     Corroded     Damaged     Not Radial

**5. Roof Conditions**

- Hole     Corroded     Un-Capped Opening     Entire Underside Coated

**6. Comments**

---



---



---



**Roof Nozzles and Appurtenances (Measure one and give quantity for peripheral vents)**

	Type	Size	Radius*	Comment
A	Nozzle	8.00 "	0.00'	
B	Nozzle	4.00 "	5.00'	
C	Coupling	2.00 "	5.00'	
D	Nozzle	4.00 "	3.50'	
E	Nozzle	4.00 "	3.50'	
F	Nozzle	4.00 "	3.50'	
G	Nozzle	4.00 "	4.00'	
H	Nozzle	4.00 "	4.00'	
I	Nozzle	4.00 "	6.00'	
J	Manway	20.00 "	5.00'	
K				
L				

Estimate Radius from Center

**Roof plate thickness readings**

Measure thickness every 10 feet.


Quadrant	Center	10'	20'	30'	40'	50'	60'	70'	80'	90'	Shell
North	0.249	0.247									
South		0.248									
East		0.249									
West		0.250									





Quadrant											
North											
South											
East											
West											


Minimum Thickness written in **Blue Font**



True North



-  - Sump
-  - Vertical Weld
-  - Patch Plate
-  - Soilside Area

		Job No:	652009
		Date:	06-08-2021
		Tank Num:	DVOP8
Customer:	AGP		
Location:	Hastings, NE		
Diameter:	12.00	Height:	42.00
Drawn by:	J. Bachman	Rev:	

### 1. Tank Bottom

- Annular Ring  Water Washed  Blasted  Product Residue  Dirt/Debris  
 Heavy Rust Scale  Standing Water  Heavy Product (Not Inspected)

### 2. Undesirable Bottom Conditions

See Layout and X,Y Sheet for locations

- Lap Seam Corrosion  Cornerweld Corrosion  Weld Pinholes  Weld Cracks  
 Gouges  Inactive Corrosion  Active Corrosion  Welds Not Inspected  
 Isolated Pitting  Areas of Pitting  Hole(s)

**Topside Thresholds: Inner Plates: 0.100" Sketch Plates: 0.100" Critical Zone: 0.080"**

**Deepest Pitting found: \_\_ Plate Number: \_\_ General Pitting: \_\_**

There were no topside pits detected below the thresholds. A 5-year inspection interval was used.

### 3. Coating Conditions

None  Thin  Thick

Coating Thickness \_\_ mils  Peeling  Cracking  Holidays  Blistered  
\_\_ # Areas Removed  Needs Further Testing  Needs Repair  Needs Replacement

### 4. Inspection Methods

See Layout and X,Y Sheet for locations

- Ultrasonic Edge Scrubs Thickness Range: 0.150-0.260" Thinnest Area Found: \_\_\_\_\_  
 MFL 100 % of Bottom  Isolated Corrosion  Areas of Corrosion

**Soilside Thresholds: Inner Plates: 0.150" Sketch Plates: 0.150" Critical Zone: 0.170"**

**Thinnest Area Found: 0.130" Plate Number: 2 General Loss: \_\_**

- Vacuum Box  Lap Seams  Pad Plates  Patch Plates  Leaks Found  
 MT/PT  Cornerweld  Lap Seams  Pad Plates  Patch Plates  Cracks Found

There were three areas of soilside corrosion below the thresholds. One repair area was located in the critical zone. These areas were marked for repair. A 5-year inspection interval was used.

### 5. Sump

(thicknesses on UES Sump form)

Quantity: 1

- Hole  Corrosion  Coated  Water/Product  Patched  Not Inspected

### 6. Settlement

Measure on Survey Page

- Humps  Sags  Edge Settlement >3/8" Per Foot  Needs Evaluation

A settlement survey was not performed.


**UES Thickness Scrubs**

MinThickness 0.150 Max Thickness 0.260

Enter Ultrasonic Edge Scrub thicknesses (UES) 12"x12" at each station

Station	Min	Max	Station	Min	Max	Station	Min	Max
1	0.250	0.260	11			21		
2	0.150	0.250	12			22		
3	0.250	0.260	13			23		
4	0.250	0.260	14			24		
5	0.230	0.250	15			25		
6	0.250	0.260	16			26		
7	0.250	0.260	17			27		
8	0.190	0.250	18			28		
9			19			29		
10			20			30		

**Sump Inspection** Size: 36"x14"



	Center	North	South	East	West
1	0.340				
2		0.345	0.350	0.340	0.355
3		0.348	0.340	0.344	0.349
4		0.350	0.340	0.345	0.345

Bottom or Dish Sump

	North	South	East	West
1				
2				
3				
4				

Sump side walls

STI-INTERNAL



Company: AGP

Location: Hastings, NE

Job ID: 652009

Date: 6/8/2021

Tank: DVOP8

MinThickness 0.240

Max Thickness 0.248

AVG Thickness 0.244

Enter plate thicknesses

Plate	t	Plate	t	Plate	t	Plate	t	Plate	t
1	0.240	41		81		121		161	
2	0.248	42		82		122		162	
3		43		83		123		163	
4		44		84		124		164	
5		45		85		125		165	
6		46		86		126		166	
7		47		87		127		167	
8		48		88		128		168	
9		49		89		129		169	
10		50		90		130		170	
11		51		91		131		171	
12		52		92		132		172	
13		53		93		133		173	
14		54		94		134		174	
15		55		95		135		175	
16		56		96		136		176	
17		57		97		137		177	
18		58		98		138		178	
19		59		99		139		179	
20		60		100		140		180	
21		61		101		141		181	
22		62		102		142		182	
23		63		103		143		183	
24		64		104		144		184	
25		65		105		145		185	
26		66		106		146		186	
27		67		107		147		187	
28		68		108		148		188	
29		69		109		149		189	
30		70		110		150		190	
31		71		111		151		191	
32		72		112		152		192	
33		73		113		153		193	
34		74		114		154		194	
35		75		115		155		195	
36		76		116		156		196	
37		77		117		157		197	
38		78		118		158		198	
39		79		119		159		199	
40		80		120		160		200	

Enter plate number and A, B, C to identify patch plate. Put patch plate location and letter on drawing. Enter existing plate thicknesses scrub range below.

Plate #	Min	Max	Plate #	Min	Max	Plate #	Min	Max
1/2 A	0.240	0.250						





## Summary

The tank was located inside a building. The open vent extended to the lower level of the tank. The open vent was not vented outside the building.

The tank had an 8-inch open vent. **A UL tank of this size would require a 10-inch emergency pressure vent per UL 142, Table 8.1.**

The coating on the external shell and appurtenances was in good condition. **This should be monitored at future inspections.**

The repads of Shell Items C, I, and J did not have telltale holes. **Consideration should be given to drilling and tapping telltale holes in the repads, pressure testing the neck and repad welds.**

The weld spacing of Shell Items C and G did not meet API standards. **Since the tank shell is 0.5 inches or less in thickness, no corrective action is required.**

Shell Nozzles A, G, and H were over 2 inches in diameter and did not have repads. **Since the shell thickness is over twice the required thickness no action is required.**

There was a pinhole in the internal weld of Shell Item E. There was undercut and pinholes in the internal welds of Shell Items F. **Consideration should be given to weld repairing these areas.**

The coating on the external roof and appurtenances was in like new condition. **This should be monitored at future inspections.**

There was a patch plate located on the underside of the tank and welded to the topside. **This should be monitored at future inspections.**

A visual inspection was performed on the tank bottom to locate topside pits 0.100 inches deep and deeper in the bottom plates and 0.080 inches deep and deeper in the critical zone (within three inches of the shell) for a 5-year inspection interval. There were no pits detected below the thresholds. **No action is required.**

A Magnetic Flux Leakage (MFL) scan was performed on approximately 100 percent of the tank bottom at a remaining wall threshold of 0.150 inches thick in the bottom plates and 0.170 inches thick in the critical zone (within three inches of the shell) for a 5-year inspection interval. There were three areas of soilside corrosion below the thresholds. One repair area was located in the critical zone. These areas were marked for repair. The lowest readings were 0.130 inches and located on Bottom Plate 2. **The corroded areas were patched per API 653 standards. The tank should be reinspected internally in 2026 and reevaluated.**

Ultrasonic Edge Scrubs (UES) were performed around the entire circumference of the tank. The thicknesses ranged from 0.150 to 0.260 inches. Corrosion below the thresholds was found. **The corroded areas were patched per API 653 standards.**

The dish-shaped sump was 36 inches in diameter and 14 inches deep. The thicknesses ranged from 0.340 to 0.355 inches. No corrosion was detected. There was product in the sump.

An ultrasonic thickness reading was taken at random on each bottom plate. The thickness readings were 0.240 and 0.248 inches.

A settlement survey was not performed.

Inserv utilizes certified inspectors (STI and API-653) to perform small tank inspections in compliance with industry standards such as SP001 and API-653. The tank was categorized and inspection intervals determined per STI's SP001, 5th Edition, Table 5.5.


Tank DVOP8 had a capacity of 35,291 gallons, a containment area and a CRDM (RPB, concrete pad), making it a Category 1 tank. The tank still requires periodic inspections by the owner's inspector per SP001. **The next inspection required by is an internal inspection due in 2026.**

## Vertical Tank Thickness and Venting

(Not under pressure, Hydraulic head pressure only)

**Inputs:**

No	Rectangular Tank?	
No	Elevated Tank	
No	Stainless Steel Tank	
42.00	(ft) H	Tank Height
12.00	(ft) D	Tank Diameter <span style="border: 1px solid black; padding: 0 5px;">5.98</span> (ft) Ri Inside radius
0.70	E	Joint efficiency (use 1 for butt weld, 0.70 for lap welds)
23600	S	Allowable stress (Use 23600 if unknown steel)
62.4	lb/cf	Density of product (use 62.4 for water if unknown)
42	(ft) Hp	Height of product when full (inside tank shell)
0.245	(in) Tsm	Measured minimum thickness on shell
0.247	(in) Trm	Measured minimum thickness on roof
0.155		



**Tank Properties**

35291.71	Gal	Tank Capacity
1130.97	sq ft	Wetted area per UL-142
18.20	P	Internal Hydraulic Pressure (P= H(lbs/cf)/144)

**Shell Circumferential Stress (longitudinal Joint) Note:1**

0.167	(in) Tsl	Required thickness = $12 \cdot P \cdot Ri / (S \cdot E - 0.6 \cdot P)$ or 0.167 inches min per UL-142
-------	----------	---

**Shell Longitudinal Stress (Circumferential Joint) Note: 1**

0.167	(in) Tsc	Required thickness = $12 \cdot P \cdot Ri / (S \cdot E - 0.4 \cdot P)$ or 0.167 inches min per UL-142
-------	----------	---

**Required Venting**

4.00	(in)	<b>Minimum Normal Vent per UL142 Table 8.2 Note:3</b>
10.00	(in)	<b>Minimum Emergency Vent per UL142 Table 8.1 Note:4</b>

**Shell Thickness evaluation per STI-SP001 4th Ed. Section10**

0.167	(in) Tsr	Required shell thickness Maximum of Tsl and Tsc
0.245	(in) Tsm	Measured thickness

**Shell Thickness is Okay all Categories**

**Shell Thickness is Okay Category 1**

**Shell Thickness is Okay Category 1**

0.1253	75% of required thickness
0.0835	50% of required thickness
0.0418	25% of required thickness

**Roof Thickness evaluation per STI-SP001 4th Ed. Section10**

0.123	(in) Trr	Required roof thickness
0.247	(in) Trm	Measured roof thickness

**Roof Thickness is Okay all Categories**

**Roof Thickness is Okay Category 1**

**Roof Thickness is Okay Category 1**

0.0923	75% of required thickness
0.0615	50% of required thickness
0.0308	25% of required thickness

Note: 1 ASME Boiler and Pressure Vessel Code Division I, Section 8 (1986)

Note: 2 STI SP001 4th edition

Note: 3 UL-142 8th edition July 11, 2002 Tables 15.1, 8.1, 8.2



IMG\_1062



IMG\_1060




IMG\_1061



IMG\_1063



IMG\_1064



IMG\_1065





IMG\_1066



IMG\_1067



IMG\_1068



IMG\_1069




IMG\_1070



IMG\_1071



IMG\_1072



IMG\_1073



IMG\_1074



IMG\_1075



IMG\_1076



IMG\_1077





IMG\_1078



IMG\_1079



IMG\_1080



IMG\_1081



IMG\_1082



IMG\_1083





IMG\_1084



IMG\_1085



IMG\_1086



IMG\_1087



IMG\_1088




IMG\_1089






IMG\_1090



IMG\_1091



IMG\_1092



IMG\_1127



IMG\_1128



IMG\_1129




IMG\_1130




IMG\_1131



IMG\_1132



IMG\_1133




IMG\_1134




IMG\_1135





IMG\_1136




IMG\_1137




IMG\_1138



IMG\_1139




IMG\_1140




IMG\_1141







IMG\_1142



IMG\_1143




IMG\_1144



IMG\_1145




IMG\_1093



IMG\_1197





IMG\_1094



IMG\_1198



IMG\_1095



IMG\_1096



IMG\_1097



IMG\_1098





IMG\_1099



IMG\_1100



IMG\_1101



IMG\_1102



IMG\_1103



IMG\_1104





IMG\_1105



IMG\_1106



IMG\_1107



IMG\_1108



IMG\_1109



IMG\_1110






IMG\_1111




IMG\_1112



IMG\_1113



IMG\_1114



IMG\_1115



IMG\_1116





IMG\_1117



IMG\_1118



IMG\_1119



IMG\_1120




IMG\_1121



IMG\_1122





IMG\_1123



IMG\_1124



IMG\_1125



IMG\_1126



IMG\_1223



IMG\_1224





IMG\_1360



IMG\_1361



IMG\_1362



IMG\_1363



IMG\_1364



IMG\_1365






IMG\_1366



IMG\_1367



IMG\_1368



20210611\_114315



20210611\_114330



20210611\_114336



20210611\_114344




Dear Mr. Martin:

Congratulations on passing STI SP001 Adjunct online certification course. Below is your STI Inspector identification card and certificate. We suggest that you print this page and:

- Cut out and laminate the ID card
- Frame the certificate

If you have any questions about this or any field related inspection, please feel free to call Joseph Mentzer, STI Project Engineer, at (224) 286-6469.





# API Individual Certification Programs

verifies that

*James William Martin*

has met the requirements for API certification

*API-653 Aboveground Storage Tank  
Inspector*

Certification Number      *32455*

Original Certification Date      *April 30, 2008*

Current Certification Date      *April 30, 2020*

Expiration Date      *April 30, 2023*



Manager, Individual Certification Programs

# ULTRASONIC TESTING

THIS ACKNOWLEDGES THAT

**James Martin**

HAS SUCCESSFULLY COMPLETED THE REQUIREMENTS OF INSERV INSPECTION AND CONSULTING SERVICES LLC  
QUALIFICATION AND CERTIFICATION OF NDE PERSONNEL WRITTEN PRACTICE REFERENCING ASNT-TC-1A

**LEVEL II**

**DECEMBER  
9<sup>TH</sup> 2020**

x

SIGNED, *James Martin*  
Authorized NDT Level III

**INSERV**

INTEGRATED SERVICE COMPANY LLC