

**Tank Inspector(s)** J. Martin (STI #AC 32455) and M. Emert

**Name Plate/Construction**

**Circumference:** 37.75'

Steel  Stainless Steel  Plastic  Aluminum  Fiberglass

Build Date 2000 Manufacturer Palmer Manufacturing and Tank

Build Std:  API-650  API-12C  API-12F  UL-142  Re-Erected  Unknown

Date Last External \_\_\_\_\_ Date Last Internal \_\_\_\_\_

**Name Plate Data**

Dia/Width: 12.00 ft Must be <=30 ft

Height: 42.00 ft Must be <=50 ft

Length: \_\_\_\_\_ ft

Capacity: 35,291 GAL

STI Not applicable for tanks over 50,000 Gal.

**Product Service** Basestock

**Specific Gravity** 1.00

Ambient  Heated

Refrigerated

Operating Temperature \_\_\_\_\_ F

STI Not applicable for heated tanks over 200°F



**Tank Description**

Vertical  Horizontal  Box  Tote  Other \_\_\_\_\_

**Foundation:**  Grade  Ringwall  Concrete Pad  Saddles  Skids  Other

**Bottom:**  Welded  Riveted  Bolted  N/A Year Installed: \_\_\_\_\_

No Coating  Thin Coating  Thick Coating

Pan Type  Cathodic Protection  Double Bottom  Leak Detection

**Shell:**  Welded  Riveted  Bolted  Combination

Lap welded  Insulated  Double Wall  Containment Vessel

**Horizontal Tank Heads:**  Flat  Hemispherical  Dish

**Roof:**  Cone  Flat  Geo-Dome  Dome  Open/None  N/A

**Roof Access:**  Spiral Stair  Radial Stair  Catwalk  Ladder  None

**1. Spill Control**  None

- Containment AST  Dbl Wall/Bottom  Dike Area  Remote Impound  in Building

**2. CRDM (Continuous Release Detection Method)**  None

**RPB (Release Prevention Barrier)**

Type  Concrete Pad  Liner  Steel Plate  Other \_\_\_\_\_

**Double Wall/Bottom** with Interstitial Space

OK  Not OK  Not Checked

**Elevated**

**3. AST Category** Category   1  

- 1 Any Tank with Both Spill Control and CRDM
  - 2 Single wall AST in contact with ground NO CRDM Has Spill Control
  - 3 Single wall AST in contact with ground has CRDM NO Spill Control
- Vertical AST on concrete pad CRDM has NO Spill Control  
Single/Double wall AST Has CRDM NO Overfill Protection

**4. Venting**

- Open vents not elevated 12 feet  Open vents not vented outside building  
 Uses long bolted Manway as emergency vent  Vapor recovery system

Primary Vent  Open  Pressure/Vacuum  Pressure Size:   8.00"  

Secondary Vent  Open  Pressure/Vacuum  Pressure Size: \_\_\_\_\_

Emergency Vent  Open  Pressure/Vacuum  Pressure Size: \_\_\_\_\_

Interstice Vent  Open  Pressure/Vacuum  Pressure Size: \_\_\_\_\_

**5. Comments**

The tank was located inside a building. The open vent was not vented outside the building.

The tank had an 8-inch open vent.

**1. Foundation** **Concrete Pad**

**Anchorage:**  No Anchors  Cable Tie Downs  Anchor Bolts  
Number of Anchors: 4 Size of Bolt (in) 1.00 Height (in) 14.00  
Thickness of top plate (In) 0.509 Thickness of side plate (In) 0.520

**Ringwall/Pad Dimensions:** Distance from Bottom extension to edge (in) 5.00 Min 6.00 Max  
Distance from top surface to grade (in) 23.00 Min 26.00 Max

**Support Dimensions:** Number of supports:    Space between Supports (in)     
Size of supports (in):    Height of supports (in):     
 No Pad Plate  Pad Plate  Stitch welded pad plate  Seal welded pad plate

**2. Undesirable Foundation Conditions**

- Grade against tank  Washout  Voids under tank  Hairline Cracks in concrete
- Large Cracks in concrete (>1/8")  Exposed rebar  Discontinuous Ringwall
- Corrosion of supports  Anchor Bolt Corrosion  Bottom extension corrosion

**3. Undesirable Area Conditions**

- Obvious settlement  Water Against tank  Drainage toward tank  Excessive debris
- Vegetation by tank  Moss under bottom  No Containment Dike/Wall
- Damaged Containment Dike/Wall  Product residue  Wet Product by Tank

**4. Comments**

The tank was located inside a building.

---

---

---

---

---

---

---

---

---

---

**1. External Tank Shell**

*Welded*

- Seams Covered  Rivets Unsealed  Rivets Sealed  Rivets Welded
- No Pad Plates Under Shell Brackets  No Ice shields on All Item <2"  Foam System

**2. Coating Conditions**

Like New  Good  Fair  Poor  No Coating

- Peeling  Cracking  Thinning  Rust Stained  Primer Only  Areas not Coated

**Insulation Conditions**

Like New  Good  Fair  Poor

- Sprayed  Corrugated/ Banded  Smooth Metal  Areas Removed
- Tears  Damaged  Holes  Penetrations Not Sealed  Wet under Insulation

**3. Undesirable Shell Conditions**

- Weld Seam Corrosion  Weld Pinholes  Arc Strikes  Weld Porosity  Weld Slag
- Weld Cracks  Weld Undercut  Lack of Fusion  Holes in Shell  Gouges in Shell
- Inactive Corrosion  Active Corrosion  Surface Corrosion  Corrosion Damage
- Deepest Shell Corrosion Found: \_\_ Height above Grade \_\_  Needs Evaluation

**4. Shell Distortion and Buckling**

- Peaking  Banding  Lower Shell Distortion  Upper Shell Distortion  Torn Plate
- Distortion around Nozzles/Repairs  Minor Buckles  Major Buckles  Sharp Creases

**5. Possible Improper Construction Practices**

List Items Below

- Square Corner Inserts/Pads  Lap Patches  Unreinforced Penetration  Split Repad
- No Telltale Hole in Repad  Plugged Telltale Hole in Repad  Improper Weld Space
- Insufficient Reinforcement  Undersize Insert  Cover Plate Thin  Flange Thin

The repads of Shell Items C, L, and M did not have telltale holes.

The weld spacing of Shell Items C and G did not meet API standards.

Shell Items A, H, I, and J were over 2 inches in diameter and did not have repads.

**6. Ground cables**

Quantity 1

- None Found  Not Attached  Broken  Improper Attachment

**7. Level Gauge     Manufacturer DP Harp     Product Height:      FT**

- Float with Gauge    Target Board    Electronic    Floats, Cables Guides not Attached
- Not Working    Conduit damaged    Needs Service

**8. Top Angle Wind Girder**

- None    Toe In    Toe Out    Corrosion    TA Weld Size Greater than 3/16"
- Damaged Welds    Buckled    Coating Failure    Holds Water    Buckled

**Top Angle:**   Vertical (in) 2.50   Horizontal (in) 2.50   Thickness (in) 0.263

**Wind girder:**   Vertical (in)        Horizontal (in)        Thickness (in)       
                             Distance from Top of Tank (in):     

**9. Shell Vents and Overflows**

- None    Indicator Holes    Screens Missing/Damaged    Over Stairway    Geo Dome
- Number of Vents:        Size (in):        Distance from roof (in):       
 Number of Overflows:        Size (in):        Distance from roof (in):

**10. Comments**

The coating on the external shell and appurtenances was in good condition.

---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---

**1. Internal Tank Shell** **Welded**

- Product Build-Up  Product Residue  Lower Shell Coated  Entire Shell Coated
- Shell Not Inspected  Shell Welds Not Inspected

**2. Undesirable Shell Conditions**

- Weld Seam Corrosion  Weld Pinholes  Weld Porosity  Weld Slag  Weld Cracks
  - Weld Undercut  Lack of Fusion  Arc Strikes  Holes in Shell  Gouges in Shell
  - Weld Burrs  Minor Shell Corrosion  Shell Corrosion Damage
- Deepest Shell Corrosion Found: \_\_ Height above Bottom \_\_  Needs Evaluation

**5. Possible Improper Construction Practices** List Items Below

- Lap Patches  Item Penetrates but Not Welded  Hot Tap  Drilled Hole for Coupling
  - No Pads on Gauge Pole Supports  No Pads on Datum Plate Supports  Undercut
  - Incomplete Shell Weld  Lack-of-Fusion  Cracked Weld  Welds Not Visible
- 
- 

**5. Internal Piping and Supports**

- No Pads on Pipe Supports  Pipe Support Welded to Both Pipe and Bottom
  - Inadequate Pipe Supports  Corrosion on Piping  Broken Welds  No Diffuser
  - No Suction Trough  Center Suction / Fill  Has Floating Suction Line
- 

**6. Comments**

There was product residue on the internal shell.

---

---

---

---

---

---

---



---



Height is measured from bottom to the centerline of the item. Weld spaces are measured toe-to-toe of the welds.

ID	Size	TT hole	Shape*	Description	Location	Height	Repad/Insert			Neck Thicknesses				Weld Space	To**
							Width	Height	t	Top	Bottom	Left	Right		
A	24.00			Manway	0.00	30.00				0.390				16.25	CW
B	0.75			Coupling	3.20	30.00								28.00	CW
C	2.00		A	Nozzle	5.20	6.00	10.00	10.00	0.246	0.216				0.50	CW
D	0.70			Coupling	6.40	24.00								23.00	CW
E	3.00			Nozzle	11.50	Ring 7									
F	0.75			Coupling	11.50	24.00								12.00	G
G	4.00	1	C	Nozzle	11.50	6.00	10.00	10.00	0.245					0.00	CW
H	4.00			Nozzle	13.20	32.00				0.242				28.75	CW
I	4.00			Nozzle (insulated)	14.00	20.00									
J	4.00			Nozzle	15.30	8.00				0.232				5.25	CW
K				Catwalk	21.00										
L	8.00		A	Nozzle w/ Mixer	25.80	36.00	26.00	26.00	0.250	0.292				23.75	CW
M	2.00		A	Nozzle	32.70	9.00	10.00	10.00	0.247	0.217				3.50	CW
N															
O															
P															
Q															
R															
S															
T															
U															
V															
W															
X															
Y															
Z															
AA															
BB															

\*\* TS=Tombstone or low type repad, CW=Cornerweld, HW= Horz. weld, VW=Vertical Weld, R#=Repad of Item #, #=-Weld of Item#, PB=Pan Bottom weld



- | Couplings/Other
- ┆ Nozzles
- ┆┆ Manway
- Ladder
- Catwalk/Platform
- ┌┐ Stairs

		Job No:	652130	
		Tank Num:	DVOP 9	
		Date:	07-14-2021	
Customer:	AGP			
Location:	Hastings, NE			
	Diameter:	12.00	Height:	42.00
	Drawn by:	A Frye	Rev:	



STI-INTERNAL



Company: AGP  
 Location: Hastings, NE

Job ID: 652130  
 Date: 7/14/2021  
 Tank: DVOP 9

Course	Height (in)	Shell Material	Joint Type*	Shell Thicknesses (in)		
				Bottom	Middle	Top
1	69.00		BW	0.249	0.249	0.246
				0.250	0.250	0.250
				0.251	0.248	0.248
				0.248	0.248	0.248
2	69.00		BW	0.249	0.248	0.249
3	68.50		BW	0.249	0.249	0.248
4	68.50		BW	0.247	0.248	0.247
5	68.50		BW	0.247	0.246	0.248
6	69.00		BW	0.249	0.249	0.249
7	68.50		BW	0.246	0.247	0.248
8						
9						
10						

\* Joint Type: BW= Butt Weld, LW= Lap Weld, LR# = Lap Riveted (num of rivets), BR= Riveted Butt joint (Num Rivets on one side), BLT=Bolted

Total Height

Minimum Thickness written in **Blue Font**

Enter Vertical seam Location in CCW order from Start point.

1	36.25	11		21		31
2		12		22		32
3		13		23		33
4		14		24		34
5		15		25		35
6		16		26		36
7		17		27		37
8		18		28		38
9		19		29		39
10		20		30		40

Second Course offset \_\_\_\_\_

Third Course offset \_\_\_\_\_

**1. Tank Roof** **Cone**

- No Access  Limited Access  Access Not Safe  No Safety Tie Off  
Slope, Run 24 inches Rise (in): 3.00

**2. Coating Conditions**  Like New  Good  Fair  Poor  No Coating

- Peeling  Cracking  Thinning  Primer Only  Areas Not Coated

- Insulation Conditions**  Like New  Good  Fair  Poor  
 Sprayed  Corrugated/ Banded  Smooth Metal  Areas Removed  
 Tears  Damaged  Holes  Penetrations Not Sealed  Wet under Insulation

**3. Undesirable Roof Conditions**

- Weld Seam Corrosion  Weld Pinholes  Weld Cracks  Holes in Roof  
 Inactive Corrosion  Active Corrosion  Surface Corrosion  Corrosion Damage  
 No Safety Bars on >30" Openings Thinnest RWT Found: 0.246"  Needs Evaluation

**4. Roof Distortion and Buckling**

- Excessive Waviness  Areas Holding Water  Settlement of Support Structure  
 Torn Plates  Sharp Creases  Roof Joint Not Frangible (3/16")

**5. Vents and settings** List vent sizes and settings below

- Open Vents  Pressure/Vacuum Vents  Peripheral Vents  Flame Arrestor  
 Missing/Damaged Screens  Vents Need Service  Less than 8" Center Vent with IFR  
The tank had an 8-inch open vent. The open vent extended to the lower level of the tank.  
The open vent was not vented outside the building.

**6. Comments**

The coating on the external roof and appurtenances was in good condition.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**1. Internal Tank Roof**

Structurally Supported     Self Supporting (No Structure)

Record column radius location and number of columns

Center	Bay 1	Bay 2	Bay 3	Bay 4
Radius    0				
Number    0				

**2. Column Type, Size and Conditions**

Structural Steel     Steel Pipe     Both Types

Dimensions (in)	Center Column	Outer Columns
Size of Members		

- Welded     Riveted     Bolted     Bowed     Twisted     Out-of-Plumb     Damaged  
 Corroded     Broken Welds     No Drain Hole in Pipe

**3. Column Base Type, Size and Conditions**

H-Shaped     T-Shaped     Flat Plate

Dimensions (in)	Center Base	Outer Bases
Size of Members		
Bearing Plate		

- Welded     Riveted     Bolted     Damaged     Welded to Bottom     No Guide Clips  
 Insufficient Guide Clips     Corroded     No Bearing Plate     Not Seal Welded

**4. Rafter Conditions**

- Bowed     Twisted     Hanging     Sagging     Corroded     Damaged     Not Radial

**5. Roof Conditions**

- Hole     Corroded     Un-Capped Opening     Entire Underside Coated

**6. Comments**

---



---



---

**Roof Nozzles and Appurtenances (Measure one and give quantity for peripheral vents)**

	Type	Size	Radius*	Comment
A	Nozzle	8.00 "	0.00'	
B	Nozzle	6.00 "	5.00'	
C	Coupling	2.00 "	5.00'	
D	Nozzle	6.00 "	4.50'	
E	Nozzle	6.00 "	4.00'	
F	Manway	20.00 "	4.50'	
G	Nozzle	6.00 "	3.50'	
H	Nozzle	6.00 "	4.00'	
I	Nozzle	6.00 "	4.50'	
J	Nozzle	6.00 "	5.00'	
K				
L				

Estimate Radius from Center

**Roof plate thickness readings**

Measure thickness every 10 feet.

Quadrant	Center	10'	20'	30'	40'	50'	60'	70'	80'	90'	Shell
North	0.246	0.250									
South											
East											
West											

Quadrant											
North											
South											
East											
West											

Minimum Thickness written in **Blue Font**

### 1. Tank Bottom

- Annular Ring  Water Washed  Blasted  Product Residue  Dirt/Debris  
 Heavy Rust Scale  Standing Water  Heavy Product (Not Inspected)

### 2. Undesirable Bottom Conditions

See Layout and X,Y Sheet for locations

- Lap Seam Corrosion  Cornerweld Corrosion  Weld Pinholes  Weld Cracks  
 Gouges  Inactive Corrosion  Active Corrosion  Welds Not Inspected  
 Isolated Pitting  Areas of Pitting  Hole(s)

**Topside Thresholds: Inner Plates: 0.075" Sketch Plates: 0.075" Critical Zone: 0.060"**

**Deepest Pitting found: \_\_ Plate Number: \_\_ General Pitting: \_\_**

There were no topside pits detected below the thresholds. A 10-year inspection interval was used.

### 3. Coating Conditions

None  Thin  Thick

Coating Thickness \_\_ mils  Peeling  Cracking  Holidays  Blistered  
\_\_ # Areas Removed  Needs Further Testing  Needs Repair  Needs Replacement

### 4. Inspection Methods

See Layout and X,Y Sheet for locations

- Ultrasonic Edge Scrubs Thickness Range: 0.200-0.260" Thinnest Area Found: \_\_\_\_\_  
 MFL 99 % of Bottom  Isolated Corrosion  Areas of Corrosion

**Soilside Thresholds: Inner Plates: 0.175" Sketch Plates: 0.175" Critical Zone: 0.190"**

**Thinnest Area Found: 0.200" Plate Number: 1 General Loss: \_\_**

- Vacuum Box  Lap Seams  Pad Plates  Patch Plates  Leaks Found  
 MT/PT  Cornerweld  Lap Seams  Pad Plates  Patch Plates  Cracks Found

There were no areas of soilside corrosion below the thresholds. A 10-year inspection interval was used.

### 5. Sump (thicknesses on UES Sump form)

Quantity: 1

- Hole  Corrosion  Coated  Water/Product  Patched  Not Inspected

### 6. Settlement

Measure on Survey Page

- Humps  Sags  Edge Settlement >3/8" Per Foot  Needs Evaluation

A settlement survey was not performed.

MinThickness 0.255

Max Thickness 0.261

AVG Thickness 0.258

Enter plate thicknesses

Plate	t	Plate	t	Plate	t	Plate	t	Plate	t
1	0.255	41		81		121		161	
2	0.261	42		82		122		162	
3		43		83		123		163	
4		44		84		124		164	
5		45		85		125		165	
6		46		86		126		166	
7		47		87		127		167	
8		48		88		128		168	
9		49		89		129		169	
10		50		90		130		170	
11		51		91		131		171	
12		52		92		132		172	
13		53		93		133		173	
14		54		94		134		174	
15		55		95		135		175	
16		56		96		136		176	
17		57		97		137		177	
18		58		98		138		178	
19		59		99		139		179	
20		60		100		140		180	
21		61		101		141		181	
22		62		102		142		182	
23		63		103		143		183	
24		64		104		144		184	
25		65		105		145		185	
26		66		106		146		186	
27		67		107		147		187	
28		68		108		148		188	
29		69		109		149		189	
30		70		110		150		190	
31		71		111		151		191	
32		72		112		152		192	
33		73		113		153		193	
34		74		114		154		194	
35		75		115		155		195	
36		76		116		156		196	
37		77		117		157		197	
38		78		118		158		198	
39		79		119		159		199	
40		80		120		160		200	

**UES Thickness Scrubs**


MinThickness 0.200 Max Thickness 0.260

Enter Ultrasonic Edge Scrub thicknesses (UES) 12"x12" at each station

Station	Min	Max	Station	Min	Max	Station	Min	Max
1	0.210	0.260	11			21		
2	0.250	0.260	12			22		
3	0.200	0.260	13			23		
4	0.250	0.260	14			24		
5	0.250	0.260	15			25		
6	0.250	0.260	16			26		
7	0.250	0.260	17			27		
8	0.250	0.260	18			28		
9			19			29		
10			20			30		

**Sump Inspection**

Size: 36"x12"



	Center	North	South	East	West
1	0.256				
2		0.260	0.260	0.261	0.259
3		0.261	0.258	0.255	0.260
4		0.264	0.262	0.260	0.257

Bottom or Dish Sump

	North	South	East	West
1	0.261	0.259	0.250	0.262
2	0.260	0.262	0.257	0.265
3	0.257	0.260	0.255	0.260
4	0.255	0.253	0.260	0.258

Sump side walls

A total of \_\_\_\_\_ areas of Topside pitting were found. \_\_\_\_\_ of those were below thresholds.

A total of \_\_\_\_\_ areas of Soilside corrosion were found. \_\_\_\_\_ of those were below thresholds.

Min RWT 0.250 Max Pit Depth 0.000


Enter topside and soilside indications (Type S=Soilside, T=Topside, B=Both Soilside and Topside, G=Gouge, D=Dent, H=Hole)


Plate	Type	Topside Depth	Soilside RWT	Critical Zone	X	Y	Ref Corner	Comments
								No indications were found below the thresholds
<b>Note:</b> All soilside repair plates are 12 by 12 inches unless otherwise noted. Isolated Topside pits can be puddle welded or patched.								TS = Tombstone shaped






True North



- R# - Radial
-  - Sump
- > - Vertical Weld

		Job No:	652130
		Date:	07-14-2021
		Tank Num:	DVOP 9
Customer:	AGP		
Location:	Hastings, NE		
Diameter:	12.00	Height:	42.00
Drawn by:	J. Bachman	Rev:	

## Summary

The tank was located inside a building. The open vent was not vented outside the building. The open vent extended to the lower level of the tank.

The tank had an 8-inch open vent. **A UL tank of this size would require a 10-inch emergency pressure vent per UL 142, Table 8.1.**

The coating on the external shell and appurtenances was in good condition. **This should be monitored at future inspections.**

The repads of Shell Items C, L, and M did not have telltale holes. **Consideration should be given to drilling and tapping telltale holes in the repads, pressure testing the neck and repad welds.**

The weld spacing of Shell Items C and G did not meet API standards. **Since the tank shell is 0.5 inches or less in thickness, no corrective action is required.**

Shell Items A, H, I, and J were over 2 inches in diameter and did not have repads. **Since the shell thickness is over twice the required thickness no action is required.**

The coating on the external roof and appurtenances was in good condition. **This should be monitored at future inspections.**

There was product residue on the internal shell.

A visual inspection was performed on the tank bottom to locate topside pits 0.075 inches deep and deeper in the bottom plates and 0.060 inches deep and deeper in the critical zone (within three inches of the shell) for a 10-year inspection interval. There were no pits detected below the thresholds. **No action is required.**

A Magnetic Flux Leakage (MFL) scan was performed on approximately 99 percent of the tank bottom at a remaining wall threshold of 0.175 inches thick in the bottom plates and 0.190 inches thick in the critical zone (within three inches of the shell) for a 10-year inspection interval. There were no areas of soilside corrosion below the thresholds. The lowest readings were 0.200 inches and located on Bottom Plate 1. **No action is required.**

Ultrasonic Edge Scrubs (UES) were performed around the entire circumference of the tank. The thicknesses ranged from 0.200 to 0.260 inches. No corrosion below the threshold were found.

The flat-bottom sump was 36 inches in diameter and 12 inches deep. The thicknesses ranged from 0.255 to 0.262 inches in the bottom of the sump and from 0.253 to 0.262 inches in the side wall. No corrosion was detected. There was product residue in the bottom of the sump.

An ultrasonic thickness reading was taken at random on each bottom plate. The thickness readings were 0.255 and 0.261 inches.

A settlement survey was not performed.

Inserv utilizes certified inspectors (STI and API-653) to perform small tank inspections in compliance with industry standards such as SP001 and API-653. The tank was categorized and inspection intervals determined per STI's SP001, 5th Edition, Table 5.5.


Tank DVOP 9 had a capacity of 35,291 gallons, a containment area and a CRDM (RPB, concrete pad), making it a Category 1 tank. The tank still requires periodic inspections by the owner's inspector per SP001. **The next inspection required by is an internal inspection due in 2031.**

## Vertical Tank Thickness and Venting

(Not under pressure, Hydraulic head pressure only)

**Inputs:**

No	Rectangular Tank?	
No	Elevated Tank	
No	Stainless Steel Tank	
42.00	(ft) H	Tank Height
12.00	(ft) D	Tank Diameter <span style="border: 1px solid black; padding: 2px;">5.98</span> (ft) Ri Inside radius
0.70	E	Joint efficiency (use 1 for butt weld, 0.70 for lap welds)
23600	S	Allowable stress (Use 23600 if unknown steel)
62.4	lb/cf	Density of product (use 62.4 for water if unknown)
42	(ft) Hp	Height of product when full (inside tank shell)
0.246	(in) Tsm	Measured minimum thickness on shell
0.246	(in) Trm	Measured minimum thickness on roof
0.155		



**Tank Properties**

35290.73	Gal	Tank Capacity
1130.97	sq ft	Wetted area per UL-142
18.20	P	Internal Hydraulic Pressure (P= H(lbs/cf)/144)

**Shell Circumferential Stress (longitudinal Joint) Note:1**

0.167	(in) Tsl	Required thickness = $12 \cdot P \cdot Ri / (S \cdot E - 0.6 \cdot P)$ or 0.167 inches min per UL-142
-------	----------	---

**Shell Longitudinal Stress (Circumferential Joint) Note: 1**

0.167	(in) Tsc	Required thickness = $12 \cdot P \cdot Ri / (S \cdot E - 0.4 \cdot P)$ or 0.167 inches min per UL-142
-------	----------	---

**Required Venting**

4.00	(in)	<b>Minimum Normal Vent per UL142 Table 8.2 Note:3</b>
10.00	(in)	<b>Minimum Emergency Vent per UL142 Table 8.1 Note:4</b>

**Shell Thickness evaluation per STI-SP001 4th Ed. Section10**

0.167	(in) Tsr	Required shell thickness Maximum of Tsl and Tsc
0.246	(in) Tsm	Measured thickness

**Shell Thickness is Okay all Categories**

**Shell Thickness is Okay Category 1**

**Shell Thickness is Okay Category 1**

0.1253	75% of required thickness
0.0835	50% of required thickness
0.0418	25% of required thickness

**Roof Thickness evaluation per STI-SP001 4th Ed. Section10**

0.123	(in) Trr	Required roof thickness
0.246	(in) Trm	Measured roof thickness

**Roof Thickness is Okay all Categories**

**Roof Thickness is Okay Category 1**

**Roof Thickness is Okay Category 1**

0.0923	75% of required thickness
0.0615	50% of required thickness
0.0308	25% of required thickness

Note: 1 ASME Boiler and Pressure Vessel Code Division I, Section 8 (1986)

Note: 2 STI SP001 4th edition

Note: 3 UL-142 8th edition July 11, 2002 Tables 15.1, 8.1, 8.2

## Bottom Corrosion Analysis

Per API 653 4th Edition April 2009 4.4.5

In the bottom corrosion analysis the following equations and variables are used.

$$O_r = \frac{\text{Min}(RT_{bc}, RT_{ip}) - MRT}{StPr + UPr} \quad StPr = \frac{T_o - RT_{ip}}{\text{Age}} \quad UPr = \frac{T_o - RT_{bc}}{\text{Age}}$$

<b>T<sub>o</sub></b>	(in)	Original nominal bottom thickness
<b>Age</b>	(yrs)	Age of Bottom Plates (May vary over bottom)
<b>MRT</b>	(in)	Minimum bottom thickness allowed after interval (per API 653 Table 4.4) 0.100 inches Bare steel or Thin coating no containment 0.050 inches Thick reinforced coating (>0.050") and no containment 0.050 inches bare steel or any coating with leak detection and containment
<b>RT<sub>ip</sub></b>	(in)	Remaining Thickness after repair of topside pitting.
<b>RT<sub>bc</sub></b>	(in)	Remaining Thickness after repair of soilside corrosion.
<b>StP<sub>r</sub></b>	(in/yr)	Maximum Topside corrosion rate after repair
<b>UP<sub>r</sub></b>	(in/yr)	Maximum Soilside corrosion rate after repair
<b>O<sub>r</sub></b>	(yrs)	Calculated inspection interval based on thresholds and repairs.

### Notes:

- 1 Critical Zone is defined as bottom area within 3 inches of the shell.
- 2 MRT in the critical zone is lesser of 1/2 bottom plate thickness (not including corrosion allowance) or the 1/2 the ring 1 shell thickness.
- 3 If an Annular ring is required by design or use, it is evaluated per API 653 4.4.6.
- 4 If the bottom is coated StP<sub>r</sub> is 0 (API RP652).
- 5 If the bottom has Cathodic Protection (CP), UP<sub>r</sub> is 0 (API RP 651).
- 6 Patch plates are evaluated for soilside corrosion with UP<sub>r</sub> minimum of RT<sub>ip</sub> or RT<sub>bc</sub> plus the thickness of the patch plate.

INTERNAL



Company: AGP

Location: Hastings, NE

Job ID: 652130

Date: 7/14/2021

Tank: DVOP 9

## Bottom Corrosion Analysis

Per API 653 4th Edition April 2009 4.4.5

### Calculated thresholds with no coating and no cathodic protection.

No Does Tank have Annular ring?

2021	(YYYY)	Year of inspection
10	(YY) O <sub>rd</sub>	Inspection Interval
None	=	Coating type
No	=	Leak Detection & Containment
No	=	Cathodic Protection (CP)

	Include ?	Year Built	Nominal Thickness (T <sub>o</sub> )	Topside Threshold (in)	Soilside Threshold (in)
Inner Plates	Yes	2000	0.250	0.075	0.175
Sketch Plates	Yes	2000	0.250	0.075	0.175
Critical zone	Yes	2000	0.250	0.060	0.190

### MRT based on type coating, LD&C and Critical zone.

0.100	MRTi	Inner plate minimum allowable thickness
0.100	MRTs	Sketch plate minimum allowable thickness
0.125	MRTa	Critical Zone minimum allowable thickness

### Age of Plates

21	AgeI
21	AgeS
21	AgeCZ

### Actual Thresholds, Minimum Thicknesses and Repair Thresholds (inches)

#### Topside Inspection Values (values in inches)

	* Inspection Threshold Used	Max Pit depth Found	Repair Threshold used	Topside RWT after Repair
Inner Plates	0.075	0.010	No Repair	Rt <sub>pi</sub> 0.240
Sketch Plates	0.075	0.010	No Repair	RT <sub>ipS</sub> 0.240
Critical zone	0.060	0.010	No Repair	RT <sub>icZ</sub> 0.240

\* Inspection threshold for topside pitting should be rounded up to nearest 0.005 inches.

#### Soilside Inspection Values (values in inches)

	Inspection Threshold Used	Min Thickness Found	Repair Threshold used	Soilside RWT after Repair
Inner Plates	0.175	0.200	No Repair	Rt <sub>bci</sub> 0.200
Sketch Plates	0.175	0.200	No Repair	RT <sub>bcs</sub> 0.200
Critical zone	0.190	0.200	No Repair	RT <sub>bcsZ</sub> 0.200

#### Repair Analysis for full inspection interval

	Patch Plate thickness	Top side Corr. Rate (StP <sub>r</sub> )	Soilside Corr. Rate (UP <sub>r</sub> )	Calculated Interval O <sub>r</sub> (years)
Inner Plates	0.250 OK	0.0005	0.0024	20.00
Sketch Plates	0.250 OK	0.0005	0.0024	20.00
Critical zone	0.250 OK	0.0005	0.0024	20.00

Next Internal inspection due in 2031





IMG\_2668



IMG\_2669



IMG\_2670



IMG\_2671




IMG\_2672




IMG\_2673



IMG\_2674



IMG\_2675




IMG\_2676



IMG\_2677



IMG\_2678



IMG\_2679






IMG\_2680



IMG\_2681



IMG\_2682



IMG\_2683



IMG\_2684



IMG\_2685



IMG\_2686



IMG\_2687




IMG\_2688



IMG\_2689




IMG\_2690



IMG\_2691






IMG\_2695



IMG\_2698



IMG\_2702



IMG\_2703



IMG\_2704



IMG\_2705





IMG\_2706




IMG\_2707




IMG\_2708



IMG\_2709



IMG\_2710



IMG\_2711






IMG\_2712



IMG\_2713



IMG\_2714



IMG\_2715




IMG\_2716



IMG\_2717





IMG\_2718




IMG\_2719




IMG\_2720



IMG\_2721



IMG\_2722



IMG\_2723






IMG\_2724



IMG\_2725



IMG\_2726



IMG\_2727



IMG\_2728



IMG\_2729






IMG\_2730



IMG\_2731



IMG\_2732



IMG\_2733



IMG\_2734



IMG\_2735





IMG\_2736



IMG\_2737



IMG\_2738



IMG\_2739



IMG\_2740



IMG\_2741



IMG\_2742



IMG\_2743



IMG\_2744



IMG\_2745



IMG\_2746




Dear Mr. Martin:

Congratulations on passing STI SP001 Adjunct online certification course. Below is your STI Inspector identification card and certificate. We suggest that you print this page and:

- Cut out and laminate the ID card
- Frame the certificate

If you have any questions about this or any field related inspection, please feel free to call Joseph Mentzer, STI Project Engineer, at (224) 286-6469.

 **STI/SPFA**  
Aboveground Tank Inspector  
Certification Program  
847/438-8265

Issue Date:  
08/23/2019

Name: **James Martin**  
STI Inspector No: **AC 44355**  
Expires: **August 23, 2024**

The person to whom this card has been issued has met the requirements to attain the STI SP001 Adjunct Certification for API 653 Inspectors.  
This certificate is dependent on an active API 653 certification.

**CERTIFICATION**

Steel Tank Institute

**James Martin**

STI Inspector No: **AC 44355**  
Expires: **August 23, 2024**

The person whose name appears on this certificate has met all of the requirements to attain the STI SP001 Adjunct Certification for API 653 Inspectors.  
This certification is dependent on an active API 653 certification.

  
\_\_\_\_\_  
Joseph Mentzer, P.E.  
Steel Tank Institute



Issue Date:  
08/23/2019

The official status of this certificate can be verified at [www.steeltank.com](http://www.steeltank.com).

# API Individual Certification Programs

verifies that

*James William Martin*

has met the requirements for API certification

*API-653 Aboveground Storage Tank  
Inspector*

Certification Number      *32455*

Original Certification Date      *April 30, 2008*

Current Certification Date      *April 30, 2020*

Expiration Date      *April 30, 2023*



Manager, Individual Certification Programs



# ULTRASONIC TESTING

THIS ACKNOWLEDGES THAT

**James Martin**

HAS SUCCESSFULLY COMPLETED THE REQUIREMENTS OF INSERV INSPECTION AND CONSULTING SERVICES LLC  
QUALIFICATION AND CERTIFICATION OF NDE PERSONNEL WRITTEN PRACTICE REFERENCING ASNT-TC-1A

**LEVEL II**

**DECEMBER  
9<sup>TH</sup> 2020**

x

SIGNED, *James Martin*  
Authorized NDT Level III

**INSERV**

INTEGRATED SERVICE COMPANY LLC