



Loss Prevention Report

The Hartford Steam Boiler Inspection and Insurance Company

Insured:
Ergon, Inc.

Client Company:
AIG, Energy and Engineered Risk

Location:
Ergon BioFuels, LLC
1833 Haining Rd Vicksburg,
MS 39183

HSB ID No.:
HN-5900154

Conferred With:
Garrett Moore

HSB Location No.:
00049

Service Date:
April 12, 2018

HSB Representative:
Christopher Crumedy

Inspection Summary

Your plant was visited to perform annual jurisdictional boiler certificate renewal inspections. During this visit the below listed natural gas fired firetube high pressure steam boilers were examined internally within the limits of accessibility and with due regard for personal safety.

- Superior, National Board Number 16198, Year 2007
- Superior, National Board Number 16199, Year 2007

The internal inspection of the boiler included an examination of tube sheets and tubes for signs of scale accumulation, bulging, blistering or oxygen corrosion attack. The hand-hole openings were examined for a proper seating surface and wearing away due to corrosion or erosion. There was no evidence of active oxygen corrosion in the watersides of this boiler. There have been no reported low water conditions since the last certificate inspection.

The boiler furnace was internally inspected and found to be in good condition. The safety valves were sent out to be tested. All boiler controls and fuel components followed ASME CSD-1.

There were no prior outstanding recommendations. Therefore, the necessary report has been submitted to the jurisdictional boiler division to issue the Certificate of Operation.



Ergon, Inc.
April 12, 2018
Page 2

Inspected Equipment

Object Description:	Jurisdiction or Designating Number:	Type of Inspection:	Specific Location:
Firetube Boiler	MS011408-10P	Internal (certificate)	BLRM.
Firetube Boiler	MS011409-10P	Internal (certificate)	BLRM.

Comments

Thank you for the cooperation received during this inspection. Should you have any questions or comments concerning this inspection or recommendations made, please contact the HSB Hot Line at 1-800-333-4677 for assistance.



POL - 5900154

LOC - 00049

THIS REPORT HAS BEEN DISTRIBUTED TO:

DARRELL WILLIAMS
AIG, ENERGY AND ENGINEERED RISK
ELECTRONIC COPY
DARRELL.WILLIAMS@AIG.COM
COPIES = 00

BILL LIGON
LOCKTON
ELECTRONIC COPY
BLIGON@LOCKTON.COM
COPIES = 00

GARRETT MOORE
ERGON
1833 HAINING RD
VICKSBURG, MS 39183
COPIES = 01

HOUSTON EZELL
ERGON, INC.
ELECTRONIC COPY
HOUSTON.EZELL@ERGON.COM
COPIES = 00

DAVID MUSIC
HARTFORD STEAM BOILER
ELECTRONIC COPY
DAVID_MUSIC@HSB.COM
COPIES = 00

MARK KASIK
LOCKTON COMPANIES
ELECTRONIC COPY
MKASIK@LOCKTON.COM
COPIES = 00

BRODY MCCREARY
ERGON, INC.
ELECTRONIC COPY
BRODY.MCCREARY@ERGON.COM
COPIES = 00

NICOLE JONES
ERGON, INC.
ELECTRONIC COPY
NICOLE.JONES@ERGON.COM
COPIES = 00

DAVID PUGH
ERGON, INC.
ELECTRONIC COPY
DAVID.PUGH@ERGON.COM
COPIES = 00

NEEL STEWART
ERGON, INC.
ELECTRONIC COPY
NEEL.STEWART@ERGON.COM
COPIES = 00

PEYTON RANDOLPH
ERGON, INC.
ELECTRONIC COPY
PEYTON.RANDOLPH@ERGON.COM
COPIES = 00

JACQUI SINGER
AIG, ENERGY AND ENGINEERED RISK
ELECTRONIC COPY
JACQUI.SINGER@AIG.COM
COPIES = 00

JOSH MCCOOL
ERGON, INC.
ELECTRONIC COPY
JOSH.MCCOOL@ERGON.COM
COPIES = 00

PRISCILLA JIMENEZ
AIG, ENERGY AND ENGINEERED RISK
ELECTRONIC COPY
PRISCILLA.JIMENEZ@AIG.COM
COPIES = 00

t c